

MONUMENT RECORD

CORNER I.D.

0 - 21



STATE OF INDIANA - COUNTY OF MONROE

SECTION ~~21~~ 27, TOWNSHIP 8 NORTH, RANGE 2 WEST


MONUMENT DESCRIPTION & REMARKS

PIPE PLACED FLUSH IN CENTERLINE OF PAVEMENT. IT WAS NOT
CHECKED TO NORTH OR SOUTH, BUT WAS CHECK-CHAINED TO EAST
AND WEST 2642.2' TO SW AND SE CORNERS OF SECTION 27.

RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, _____ HEREBY CERTIFY THAT THIS
DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE
WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF
THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND
THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL
THIS _____ DAY OF _____, 19 _____ A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TITLE _____

TOWNSHIP:
VAN BUREN

CORNER I.D.


0 - 21

SECTION 27
 TOWNSHIP 8N
 RANGE 2W
 RS10002228

22

28

26



AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74 SURVEY PARTY T. Daugherty - H. Sudbury

COMMENTS pipe placed flush in \perp of PvMT. - it was not checked to North or South, but was check chained to East & west 2642.2 Feet to SW & SE corners of Sec 27.

REFERENCE SKETCH (use back if ness.)

